

FIG. 1A




FIG. 1C







FIG. 1B






FIG. 3A




FIG. 3C




FIG. 3B

Fig. 1 is a schematic cross-sectional view of a device. A material 1 is being processed by a tool 2. The tool 2 is connected to a motor 55 via a drive shaft 20. The motor 55 is housed in a casing 51. Arrows indicate the direction of material flow or processing.

FIG. 4C




FIG. 4B




FIG. 5A




FIG. 5B




FIG. 5C




FIG. 6A




FIG. 6B




FIG. 6C




FIG. 7B




FIG. 7A




FIG. 8A




FIG. 8B






FIG. 9B




FIG. 9A




FIG. 10B




FIG. 10A




FIG. 11A




FIG. 11B




FIG. 12A




FIG. 12B




FIG. 12C




FIG. 13A




FIG. 13B




FIG. 13C




FIG. 14C




FIG. 14A




FIG. 14B




FIG. 15C




FIG. 15A




FIG. 15B




FIG. 16C




FIG. 16A




FIG. 16B






FIG. 17C




FIG. 17A




FIG. 17B




FIG. 18B




FIG. 18C




FIG. 18A




FIG. 19B




FIG. 19A




FIG. 19C




FIG. 20B




FIG. 20A




FIG. 20C